

How to Identify Resource ID

For new poles, you must note the **Resource ID** created in JRM to track in IQGEO. As you probably already know, when a pole is retired, we also retire (do not reuse) the **Resource ID** and **Pole Tag**.

1. Resource ID in IQGEO - NDS Layer:



Information contained in this document is the property of Alden Systems. Copyright © 2025 Alden Systems, Inc., Reg. U.S. Pat & TM Office.



2. Resource ID in IQGEO - Pole Layer:



The Resource ID in JRM is equal to the Legacy ID in Alden One

Alden One:

Q Conversation Sea	Q Poles o	п Мар	C A3397593 Utility Pole	×		
A3397593 Utility Pole	<	Owner			A	Pole Tag
G Utility Pole Data		INT865CEG			~	A3397593
Utility Pole Attachments	0	DCTRINXA				Pole Height
Utility Pole Violations	0	Date Placed				Address
Notes	0	01/01/1968				Krick St, Decatur, IN
Documents	0					
Photos	0					
X History						
Conversation History	0	Legacy ID			8	GISID
		5626081				
		ZipCode				County
		46733				
		PoleStatus			₿	OwnerPoleNo
					~	
		LegacyPoleNo			8	

Information contained in this document is the property of Alden Systems. Copyright @ 2025 Alden Systems, Inc., Reg. U.S. Pat & TM Office.



		R	esource		Reports		Reference		Accour	nting	Ir	spection		Admin		ogout
x 🖩 🔂 S]													Show Filter 🔽	Group 🗹 Records	per page 15
der here to group	by that column															
ResourceID	Pole Number	Pole Tag	Wire Center	Owner	Acquisition I	Date Placed	Acct Company Code	Foreign	Route	Pole Height-Class	Removed	Project	Data Source	Last Insp Date	NESC Compliant	PNI ID
		1									-			_		
5626081	2622	A3397593	DCTRINXA	EQ UNITED TEL-IN		01/01/1968	T865		<u>H18</u>]	25-5	N	4131624	CTLIMPORT			
	der here to group ResourceID	S52001 2022	R Frihre to group by that column ResourceID Pole Number Pole Tag 552001 2522 A3397593	Resource ResourceD Pole Number Pole Tag Wire Center 5220031 2522 A3397593 DCTRINKA	Resource For the to group by that column ResourceID Pole Number Pole Tag Wire Center Owner EQUNITED 25222 A3397593 DCTRINKA EQUNITED TELIN	Resource Reports	Resource Reports Image: Constraint of the second sec	Resource Reports Reference Image: Control of the state	Resource Reports Reference Image: Comparison of the column Image: Comparison of the column Image: Comparison of the column ResourceD Pole Tag Wire Center Owner Acquisition [Date Placed Acct Company Code Foreign 50:5001 252:20 A3397593 DCTRINKA EQ LINITED 01/01/1968 TB65	Resource Reports Reference Account If the to group by that column ResourceID Pole Rumber Pole Tag Wire Center Owner Acquisition I Date Placed Acct Company Code Foreign Route 552001 2522 A3397593 DCTRINKA EQ UNITED 01/01/1968 T865 11.83	Resource Reports Reference Accounting If there to group by that column	Resource Reports Reference Accounting Irr If	Resource Reports Reference Accounting Inspection If the to group by that column ResourceID Pole Rumber Pole Rag Wire Center Owner Acquisition Date Paced Acct Company Code Foreign Route Pole Hoight Class Removed Project 552001 2822 A3387593 DCTRINKA EQ UNITED 01/01/1948 T865 11.03 25.5 N 4131624	Resource Reports Reference Accounting Inspection If IP C Image: Constraint of the	Resource Reports Reference Accounting Inspection Admin Image: Control of the logic of the	Resource Reports Reference Accounting Inspection Admin L Server to group by that column Image: Company Code Foreign Rode Pole Height-Class Removed Pole Tag Mark NESC Complexit Server to group by that column ResourceD Pole Height-Class Removed Pole Height-Class Removed </td

JRM Pole Summary Report:

1. To generate the **Pole Summary Report**, click on the Globe icon from the **Pole Result** window.

24.0			R	esource	R	eports		Reference		Acco	unting	In	ispection		Admin	L	ogout
ile Result	X	3													Show Filter 🗹	Group 🗹 Records	s per page
ag a column he	ader here to grou	up by that column															
	ResourceID	Pole Number	Pole Tag	Wire Center	Owner	Acquisition I	Date Placed	Acct Company Code	Foreign	Route	Pole Height-Class	Removed	Project	Data Source	Last Insp Date	NESC Compliant	PNI ID
															1		
	5626081	2622	A3397593	DCTRINXA	EQ UNITED TEL-IN		01/01/1968	T865		H181	25-5	N	4131624	CTLIMPORT			

2. Click the pole on the map (1), then in the new **Resource Details** window, click the **Pole Summary Report** icon (2). The report will populate and you'll see the **Resource ID** in the bottom right corner (3).

Reports	Reference	Accounting	Inspection	Admin	Logout
Morningstar Bird		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	C Show Resource	5 Tools Find Resource Details 1 of 1 INT865CEt Wire Center Pole No Foreign Pole No Struet Code Route Height-Class Wore	Boundaries Records 2:55/26081 DCTRINKA 2622 H183 25-5 INTRSSCEQ
Pole Summary Report State: N Vin Steet Code: Pole Add, Krick St. Decat Year: 1968 Heet TaxCode: R Ownership Nrese:CE 10% E Q UNIT Comments	Select a format Select a format Center: DCTRINXA Route: H18J Jr. Class; 25-5 Lo DE TEL-IN (TELEPHONE)	Copport State Project: 4131624 Lat., 40.8216720000	Pole # 2622 e Tag: A3397593 Long: -84.9372680000	od 51- Stans St. Bolman St. Gage Are	nt 1 INTRESCEQ
by system Attachments EQUINITED TEL-IN Height: 30 Type: Communi Descr: Insp.Company: ALDEN Project # adden c1 inv in Imsp.Company: GMMOSE Project # NATIONAL. CYCLE Voidator Company: Code: INTS Action Needed: N0 in IN	IPID: 2020 Insp Type: FACILITY Ref Type: JRMCO Insp Type: GROUNDLINE Ref Type: JRMCO Insp Type: GROUNDLINE Ref Type: JRMCO SSCED Dev Code MS Equip Field Servinty: B Request	Foreign Pole #: Request #: Date: 8/12/2013 5:22:00 PM Ref #: adden Cli #v in Date: 9/12/2014 5:7:00 AM Ref #: Date: 12/22/2024 5:5:00 AM Ref #: Equip 2: K. Closed Date:	Foreign Map #: Permit #: Duration: Duration: Duration: Toward: Closed By:		Hommetered
JRM	Ρ	age 1 of 1	Printed 7/10/2025 10:54:18 AM Resource ID 5626081	© 2025 Tom Yoff, © 2025 Microsoft Corpo	500 feet 100 m

Information contained in this document is the property of Alden Systems. Copyright @ 2025 Alden Systems, Inc., Reg. U.S. Pat & TM Office.